


440B/T-ACE DS1 XMTR Set-Up Flow Chart



- Press XMTR 1 or 2
- Change test set-up by underlining parameter (MODE, Pattern, Frame, etc.) with < > and pressing EDIT.